

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

DX599  
WSW  
1/2-1  
0.896 mi.  
4733 ft.

RESIDENCE  
2819 MERMAID AVE  
BROOKLYN, NY

NY LTANKS S107523153  
N/A

Site 1 of 5 in cluster DX

Relative:  
Higher

LTANKS:

Actual:  
3 ft.

Name: RESIDENCE  
Address: 2819 MERMAID AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0510753 / 2006-08-21  
Facility ID: 0510753  
Site ID: 356790  
Spill Date: 2005-12-14  
Spill Cause: Tank Failure  
Spill Source: Private Dwelling  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: qxabidi  
Referred To: Not reported  
Reported to Dept: 2005-12-14  
CID: 408  
Water Affected: Not reported  
Spill Notifier: Affected Persons  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-12-14  
Spill Record Last Update: 2006-08-21  
Spiller Name: VICTORIA CHCORI  
Spiller Company: RESIDENCE  
Spiller Address: 2819 MERMAID AVE  
Spiller County: 001  
Spiller Contact: VICTORIA CHCORI  
Spiller Phone: (718) 375-2731  
Spiller Extension: Not reported  
DEC Region: 2  
DER Facility ID: 306848  
DEC Memo: "Sangesland spoke to Rose Guido at Petro. She says the building has two 275 gal tanks tied together. There was a previous leak in one tank that was repaired in the past. Now there is a leak in the bottom of the second tank. Petro has called Milro to the site to vac out both tanks, they will set up a temp tank and will work on the clean up and tank repair/replacement in the next few days. \*\*\*\*\*Need to contact Milro in a few days to find out what work was done and if a digout is needed. \*\*\*\*\* 12/20/05 - Raphael Ketani. I called Milro ((800) 773-6780), but there was no one there who could tell me what was taking place at the site. I left a message for someone to call me back. I spoke to Nick Charonotoulos of PTC and he said that the two tanks had been removed, but he didn't know anything else. Anthony called me back to say that the tanks were only pumped out and not removed. He sent a FAX with the hazardous waste material manifest for the tank bottom sludge. 12/29/05 - Raphael Ketani. I left a message for Anthony of Milro to call me back regarding progress on cleaning up the spill. Anthony called me back and said that he would look into what was happening with the site. 07/18/06: This spill is transferred from Mr. Koon Tang to Q.Abidi. Called Mr. Nick (Manager) at

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

(718)628-3305 and left message to call me back. -QA 08/08/06: Called Mr. Nick and left message to call me back. -QA 08/21/06: Called Anthony (Milro Company) and left message to call me back. -QA 08/21/06: According to the letter of Mr. Nick Chronopoulos, Manager (Petro Heating Company) in which he mentioned they cleaned up all the oil and debris, at above premises. The oil in the basement fell on a concrete floor which had no cracks. All the oil was contained near the tanks and picked up. The tanks were leaking were pumped out by Milro Company and removed from the premises. Based on this information this spill is closed. -QA "

Remarks:

"TANK IS LEAKING ON THE BOTTOM. CLEAM UP IN PROGRESS"

All Materials:

Site ID: 356790  
Operable Unit ID: 1114085  
Operable Unit: 01  
Material ID: 2104166  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
Units: G  
Recovered: .00  
Oxygenate: Not reported